

EMF Survey Results

Client: **Montville Township School District**

Location Of Testing: **Lazar Middle School**

Date Of Testing: December 18, 2014

Time Of Testing: 10:00 am - 11:30 am

Weather: 35 Fahrenheit, 52 Relative Humidity, Partly Cloudy

Comments: Samples Collected At 1 Meter Above Ground And Away From Walls
Existing Overhead Power Lines Behind West Side School Still In Use, New Power Lines Are Not Operational

Date	Inside/Outside Building	Location	Milli Gause mG	Sample Number
12/18/2013	Inside Building	Room 40 Back Left	1.40	1
12/18/2013	Inside Building	Room 40 Back Right	1.40	2
12/18/2013	Inside Building	Room 40 Front Right	1.50	3
12/18/2013	Inside Building	Room 40 Front Left	1.70	4
12/18/2013	Inside Building	Room 40 Center	1.10	5
12/18/2013	Inside Building	Room 42 Back Left	0.45	6
12/18/2013	Inside Building	Room 42 Back Right	0.45	7
12/18/2013	Inside Building	Room 42 Front Right	0.45	8
12/18/2013	Inside Building	Room 42 Front Left	0.45	9
12/18/2013	Inside Building	Room 42 Center	0.30	10
12/18/2013	Inside Building	Room 44 Back Left	0.40	11
12/18/2013	Inside Building	Room 44 Back Right	1.10	12
12/18/2013	Inside Building	Room 44 Front Right	0.40	13
12/18/2013	Inside Building	Room 44 Front Left	0.30	14
12/18/2013	Inside Building	Room 44 Center	0.30	15
12/18/2013	Inside Building	Room 46 Back Left	0.70	16
12/18/2013	Inside Building	Room 46 Back Right	0.60	17
12/18/2013	Inside Building	Room 46 Front Right	0.50	18
12/18/2013	Inside Building	Room 46 Front Left	0.70	19
12/18/2013	Inside Building	Room 46 Center	0.50	20
12/18/2013	Inside Building	Room 48 Back Left	0.70	21

12/18/2013	Inside Building	Room 48 Back Right	0.90	22
12/18/2013	Inside Building	Room 48 Front Right	0.60	23
12/18/2013	Inside Building	Room 48 Front Left	0.60	24
12/18/2013	Inside Building	Room 48 Center	0.50	25
12/18/2013	Inside Building	Room 50 Back Left	0.60	26
12/18/2013	Inside Building	Room 50 Back Right	0.60	27
12/18/2013	Inside Building	Room 50 Front Right	0.50	28
12/18/2013	Inside Building	Room 50 Front Left	0.60	29
12/18/2013	Inside Building	Room 50 Center	0.50	30
12/18/2013	Inside Building	Room 52 Back Left	0.65	31
12/18/2013	Inside Building	Room 52 Back Right	0.50	32
12/18/2013	Inside Building	Room 52 Front Right	0.50	33
12/18/2013	Inside Building	Room 52 Front Left	0.50	34
12/18/2013	Inside Building	Room 52 Center	0.50	35
12/18/2013	Inside Building	Room 54 Back Left	0.65	36
12/18/2013	Inside Building	Room 54 Back Right	1.20	37
12/18/2013	Inside Building	Room 54 Front Right	1.20	38
12/18/2013	Inside Building	Room 54 Front Left	0.60	39
12/18/2013	Inside Building	Room 54 Center	0.40	40
12/18/2013	Inside Building	Room 56 Back Left	1.20	41
12/18/2013	Inside Building	Room 56 Back Right	0.50	42
12/18/2013	Inside Building	Room 56 Front Right	0.20	43
12/18/2013	Inside Building	Room 56 Front Left	1.30	44
12/18/2013	Inside Building	Room 56 Center	0.40	45
12/18/2013	Inside Building	Room 58 Back Left	0.60	46
12/18/2013	Inside Building	Room 58 Back Right	0.50	47
12/18/2013	Inside Building	Room 58 Front Right	0.60	48
12/18/2013	Inside Building	Room 58 Front Left	0.30	49
12/18/2013	Inside Building	Room 58 Center	0.35	50
12/18/2013	Inside Building	Room 60 Back Left	1.10	51
12/18/2013	Inside Building	Room 60 Back Right	0.60	52
12/18/2013	Inside Building	Room 60 Front Right	0.30	53
12/18/2013	Inside Building	Room 60 Front Left	0.35	54
12/18/2013	Inside Building	Room 60 Center	0.30	55
12/18/2013	Inside Building	Room 62 Back Left	1.20	56
12/18/2013	Inside Building	Room 62 Back Right	0.25	57
12/18/2013	Inside Building	Room 62 Front Right	0.20	58
12/18/2013	Inside Building	Room 62 Front Left	0.30	59
12/18/2013	Inside Building	Room 62 Center	0.30	60
12/18/2013	Inside Building	Room 64 Back Left	1.00	61
12/18/2013	Inside Building	Room 64 Back Right	0.50	62

12/18/2013	Inside Building	Room 64Front Right	0.40	63
12/18/2013	Inside Building	Room 64 Front Left	0.25	64
12/18/2013	Inside Building	Room 64 Center	0.30	65
12/18/2013	Inside Building	Main Office Back Left	1.40	66
12/18/2013	Inside Building	Main Office Back Right	1.40	67
12/18/2013	Inside Building	Main Office Front Right	1.50	68
12/18/2013	Inside Building	Main Office Front Left	1.30	69
12/18/2013	Inside Building	Main Office Center	1.10	70
12/18/2013	Inside Building	Utility Room #5 Back Left	14.50	71
12/18/2013	Inside Building	Utility Room #5 Back Right	3.00	72
12/18/2013	Inside Building	Utility Room #5 Front Right	1.00	73
12/18/2013	Inside Building	Utility Room #5 Front Left	5.00	74
12/18/2013	Inside Building	Utility Room #5 Center	6.00	75
12/18/2013	Inside Building	Main Electic Closet Back Left	110.00	76
12/18/2013	Inside Building	Main Electic Closet Back Right	85.00	77
12/18/2013	Inside Building	Main Electic Closet Front Right	20.00	78
12/18/2013	Inside Building	Main Electic Closet Front Left	25.00	79
12/18/2013	Outside Building	South East Corner By Room 40	0.50	80
12/18/2013	Outside Building	Room 44	0.80	81
12/18/2013	Outside Building	Room 50	0.85	82
12/18/2013	Outside Building	Room 56	0.70	83
12/18/2013	Outside Building	North West Corner By Room 64	0.45	84
12/18/2013	Outside Building	Room 65	0.50	85
12/18/2013	Outside Building	Room 17	0.80	86
12/18/2013	Outside Building	Cafeteria Corner North West Corner	0.80	87
12/18/2013	Outside Building	Cafeteria Corner North East Corner	1.20	88
12/18/2013	Outside Building	Cafeteria Corner South East Corner	1.20	89
12/18/2013	Outside Building	Room 7	1.30	90
12/18/2013	Outside Building	Office 1	1.40	91
12/18/2013	Outside Building	South East Corner	1.20	92
12/18/2013	Outside Building	Transformer Pole South East Corner Parking Lot	18.50	93
12/18/2013	Outside Building	South East Corner At Changebridge Road	1.40	94
12/18/2013	Outside Building	Transformer Southside By Rm 37 Back Left	7.50	95
12/18/2013	Outside Building	Transformer Southside By Rm 37 Back Right	42.00	96
12/18/2013	Outside Building	Transformer Southside By Rm 37 Front Right	110.00	97
12/18/2013	Outside Building	Transformer Southside By Rm 37 Front Left	7.00	98
12/18/2013	Outside Building	Boiler Rm #2 Door	12.00	99
12/18/2013	Outside Building	Room 37 South Corner	1.00	100
12/18/2013	Outside Building	South Ball Field Pitchers Mound	0.60	101
12/18/2013	Outside Building	South Ball Field At Tree Line Behind 3rd Base	5.00	102
12/18/2013	Outside Building	North Ball Field Pitchers Mound	1.20	103

12/18/2013	Outside Building	North Ball Field at Tree Line By 1st Base	7.00	104
12/18/2013	Outside Building	North West Corner Property Under Existing Power Lines	16.50	105
12/18/2013	Outside Building	North West Corner Property Under Existing Power Lines Perpendicular 1st Base	21.00	106
12/18/2013	Outside Building	North West Corner Property Under New Power Line	2.00	107
12/18/2013	Outside Building	South West Property Under New Power Line Pole	2.00	108
12/18/2013	Outside Building	South West Property Under New Power Lines	2.00	109
12/18/2013	Outside Building	South West Corner Property Behind South Ballfield	10.00	110
12/18/2013	Outside Building	South West Corner By 1st Base and Outfield By Woods	6.50	111
12/18/2013	Outside Building	South Ball field Home Plate	4.00	112
12/18/2013	Outside Building	South West Corner Property Behind South Ball Field and Maintenance Fence	2.00	113
12/18/2013	Outside Building	South East Corner Building Outfield South Ball Field 100 Feet	0.40	114
12/18/2013	Outside Building	North East Corner Cafeteria To Changebridge Road At Blinker Light	7.00	115