

EMF Survey Results

Client: **Montville Township School District**
Location Of Testing: **Woodmont Elementary School**

Date Of Testing: May 6, 2014
Time Of Testing: 12:30 pm - 2:30 pm
Weather: 65 Fahrenheight, 27 Relative Humidity, Sunny

Comments: Samples Collected At 1 Meter Above Ground And Away From Walls

Test Date	Inside/Outside Building	Location	Sample Number	05/06/14 Sampling Date Milli Gause mG
5/6/2014	Inside Building	Room 15 Back Left	1	1.80
5/6/2014	Inside Building	Room 15 Back Right	2	2.10
5/6/2014	Inside Building	Room 15 Front Right	3	2.10
5/6/2014	Inside Building	Room 15 Front Left	4	2.10
5/6/2014	Inside Building	Room 15 Center	5	1.90
5/6/2014	Inside Building	Room 16 Back Left	6	0.60
5/6/2014	Inside Building	Room 16 Back Right	7	0.25
5/6/2014	Inside Building	Room 16 Front Right	8	0.65
5/6/2014	Inside Building	Room 16 Front Left	9	0.60
5/6/2014	Inside Building	Room 16 Center	10	0.40
5/6/2014	Inside Building	Room 21 Back Left	11	0.60
5/6/2014	Inside Building	Room 21 Back Right	12	1.20
5/6/2014	Inside Building	Room 21 Front Right	13	2.40
5/6/2014	Inside Building	Room 21 Front Left	14	2.20
5/6/2014	Inside Building	Room 21 Center	15	0.70
5/6/2014	Inside Building	Room 23 Back Left	16	0.70
5/6/2014	Inside Building	Room 23 Back Right	17	0.25
5/6/2014	Inside Building	Room 23 Front Right	18	0.35
5/6/2014	Inside Building	Room 23 Front Left	19	3.00
5/6/2014	Inside Building	Room 23 Center	20	0.95
5/6/2014	Inside Building	Room 22 Back Left	21	0.15
5/6/2014	Inside Building	Room 22 Back Right	22	0.15
5/6/2014	Inside Building	Room 22 Front Right	23	0.80

Test Date	Inside/Outside Building	Location	Sample Number	05/06/14 Sampling Date Milli Gause mG
5/6/2014	Inside Building	Room 22 Front Left	24	0.20
5/6/2014	Inside Building	Room 22 Center	25	0.19
5/6/2014	Inside Building	Room 25 Back Left	26	0.50
5/6/2014	Inside Building	Room 25 Back Right	27	0.19
5/6/2014	Inside Building	Room 25 Front Right	28	0.15
5/6/2014	Inside Building	Room 25 Front Left	29	0.25
5/6/2014	Inside Building	Room 25 Center	30	0.15
5/6/2014	Inside Building	Room 30 Back Left	31	0.30
5/6/2014	Inside Building	Room 30 Back Right	32	0.25
5/6/2014	Inside Building	Room 30 Front Right	33	0.15
5/6/2014	Inside Building	Room 30 Front Left	34	0.15
5/6/2014	Inside Building	Room 30 Center	35	0.15
5/6/2014	Inside Building	Room 04 Back Left	36	0.35
5/6/2014	Inside Building	Room 04 Back Right	37	2.50
5/6/2014	Inside Building	Room 04 Front Right	38	0.40
5/6/2014	Inside Building	Room 04 Front Left	39	0.50
5/6/2014	Inside Building	Room 04 Center	40	0.30
5/6/2014	Inside Building	Computer Lab By Room 04 Back Left	41	2.50
5/6/2014	Inside Building	Computer Lab By Room 04 Back Right	42	0.55
5/6/2014	Inside Building	Computer Lab By Room 04 Front Right	43	1.10
5/6/2014	Inside Building	Computer Lab By Room 04 Front Left	44	0.40
5/6/2014	Inside Building	Computer Lab By Room 04 Center	45	0.40
5/6/2014	Inside Building	Room 05 Back Left	46	0.55
5/6/2014	Inside Building	Room 05 Back Right	47	0.60
5/6/2014	Inside Building	Room 05 Front Right	48	0.45
5/6/2014	Inside Building	Room 05 Front Left	49	0.75
5/6/2014	Inside Building	Room 05 Center	50	2.00
5/6/2014	Inside Building	Room 07 Back Left	51	1.00
5/6/2014	Inside Building	Room 07 Back Right	52	0.90
5/6/2014	Inside Building	Room 07 Front Right	53	3.50
5/6/2014	Inside Building	Room 07 Front Left	54	0.20
5/6/2014	Inside Building	Room 07 Center	55	0.35
5/6/2014	Inside Building	Room 10 Back Left	56	0.15
5/6/2014	Inside Building	Room 10 Back Right	57	0.35
5/6/2014	Inside Building	Room 10 Front Right	58	0.15
5/6/2014	Inside Building	Room 10 Front Left	59	0.15
5/6/2014	Inside Building	Room 10 Center	60	0.15
5/6/2014	Inside Building	Room 11 Back Left	61	0.55

Test Date	Inside/Outside Building	Location	Sample Number	05/06/14 Sampling Date Milli Gause mG
5/6/2014	Inside Building	Room 11 Back Right	62	0.20
5/6/2014	Inside Building	Room 11 Front Right	63	0.15
5/6/2014	Inside Building	Room 11 Front Left	64	0.15
5/6/2014	Inside Building	Room 11 Center	65	0.15
5/6/2014	Inside Building	Room 12 Back Left	66	0.40
5/6/2014	Inside Building	Room 12 Back Right	67	0.15
5/6/2014	Inside Building	Room 12 Front Right	68	0.15
5/6/2014	Inside Building	Room 12 Front Left	69	0.15
5/6/2014	Inside Building	Room 12 Center	71	0.15
5/6/2014	Inside Building	Room 13 Back Left	72	0.15
5/6/2014	Inside Building	Room 13 Back Right	73	0.40
5/6/2014	Inside Building	Room 13 Front Right	74	0.15
5/6/2014	Inside Building	Room 13 Front Left	75	0.15
5/6/2014	Inside Building	Room 13 Center	76	0.15
5/6/2014	Inside Building	Main Office Back Left	77	8.00
5/6/2014	Inside Building	Main Office Back Right	78	9.00
5/6/2014	Inside Building	Main Office Front Right	79	0.95
5/6/2014	Inside Building	Main Office Front Left	80	4.50
5/6/2014	Inside Building	Main Office Center	81	1.00
5/6/2014	Inside Building	Room 01 Lower Level Back Left	82	0.15
5/6/2014	Inside Building	Room 01 Lower Level Back Right	83	0.15
5/6/2014	Inside Building	Room 01 Lower Level Front Right	84	0.15
5/6/2014	Inside Building	Room 01 Lower Level Front Left	85	0.15
5/6/2014	Inside Building	Room 01 Lower Level Center	86	0.15
5/6/2014	Inside Building	Room 02 Lower Level Back Left	87	0.15
5/6/2014	Inside Building	Room 02 Lower Level Back Right	88	0.15
5/6/2014	Inside Building	Room 02 Lower Level Front Right	89	0.25
5/6/2014	Inside Building	Room 02 Lower Level Front Left	90	0.15
5/6/2014	Inside Building	Room 02 Lower Level Center	91	0.15
5/6/2014	Inside Building	Hallway By Nurse Office	92	1.70
5/6/2014	Inside Building	Hallway By Room 05	93	3.00
5/6/2014	Inside Building	Hallway by Electric Room 01	94	2.50
5/6/2014	Inside Building	Electric Room 01 Back Left	95	3.00
5/6/2014	Inside Building	Electric Room 01 Back Right	96	1.00
5/6/2014	Inside Building	Electric Room 01 Front Right	97	7.50
5/6/2014	Inside Building	Electric Room 01 Front Left	98	11.00
5/6/2014	Inside Building	Electric Room 01 Center	99	2.00
5/6/2014	Inside Building	Hallway By Room 10	100	0.15

Test Date	Inside/Outside Building	Location	Sample Number	05/06/14 Sampling Date Milli Gause mG
5/6/2014	Inside Building	Hallway By Room 13	101	0.20
5/6/2014	Inside Building	Custodial Room Back Left	102	0.90
5/6/2014	Inside Building	Custodial Room Back Right	103	6.00
5/6/2014	Inside Building	Custodial Room Front Right	104	9.00
5/6/2014	Inside Building	Custodial Room Front Left	105	7.50
5/6/2014	Inside Building	Custodial Room Center	106	3.50
5/6/2014	Inside Building	Hallway By Room 04	107	0.80
5/6/2014	Inside Building	Hallway By Nurse Room & Boys Room	108	10.50
5/6/2014	Inside Building	Hallway By Room 14	109	1.35
5/6/2014	Inside Building	Hallway By Electrical Closet 04 By Room 18	110	15.50
5/6/2014	Inside Building	Electrical Closet 04 Back Left	111	1.00
5/6/2014	Inside Building	Electrical Closet 04 Back Right	112	3.50
5/6/2014	Inside Building	Electrical Closet 04 Front Right	113	9.00
5/6/2014	Inside Building	Electrical Closet 04 Front Left	114	11.00
5/6/2014	Inside Building	Electrical Closet 04 Center	115	2.50
5/6/2014	Inside Building	Hallway By Electrical Closet 05	116	0.20
5/6/2014	Inside Building	Electrical Closet 05 Back Left	117	0.50
5/6/2014	Inside Building	Electrical Closet 05 Back Right	118	0.20
5/6/2014	Inside Building	Electrical Closet 05 Front Right	119	0.55
5/6/2014	Inside Building	Electrical Closet 05 Front Left	120	0.15
5/6/2014	Inside Building	Electrical Closet 05 Center	121	0.15
5/6/2014	Outside Building	South East Corner Gym By Front Entrance	122	0.20
5/6/2014	Outside Building	South West Corner By Room 01 Lower Level	123	0.15
5/6/2014	Outside Building	North West Corner By Room 02 Lower Level	124	0.15
5/6/2014	Outside Building	Outside Room 03	125	3.50
5/6/2014	Outside Building	Northside Transformer Back Left Side	126	45.00
5/6/2014	Outside Building	NorthsideTransformer Back Right Side	127	80.00
5/6/2014	Outside Building	Northside Transformer Front Right Side	128	45.00
5/6/2014	Outside Building	Northside Transformer Front Left Side	129	25.00
5/6/2014	Outside Building	Outside Room 04	130	0.75
5/6/2014	Outside Building	Outside Room 16	131	0.80
5/6/2014	Outside Building	North East Corner By Room 15	132	0.15
5/6/2014	Outside Building	Outside Room 17	133	0.30
5/6/2014	Outside Building	Outside Room 23	134	0.20
5/6/2014	Outside Building	South East Corner Room 29	135	0.20
5/6/2014	Outside Building	South West Corner Room 13	136	0.15
5/6/2014	Outside Building	Outside Room 09	137	0.65
5/6/2014	Outside Building	Southside Parking Lot At Tree Line By Garbage Collection	138	0.15

Test Date	Inside/Outside Building	Location	Sample Number	05/06/14 Sampling Date Milli Gause mG
5/6/2014	Outside Building	Property Corner By Exit on Woodmont Road	139	1.00
5/6/2014	Outside Building	Woodmont Road Under Power Line Between Entrance and Exit Driveways	140	0.60
5/6/2014	Outside Building	Property Corner By Entrance On Woodmont	141	0.20
5/6/2014	Outside Building	Northside Tree Line By Transformer	142	0.35
5/6/2014	Outside Building	Westside Playground Upper Level Center	143	0.12
5/6/2014	Outside Building	Westside Playground Swing Set Lower Level	144	0.12
5/6/2014	Outside Building	Westside Playground Lower Level	145	0.12
5/6/2014	Outside Building	Northwest Property Corner Lower Field By Fire Station	146	0.12
5/6/2014	Outside Building	Southwest Property Corner Lower Field Behind Back Stop	147	0.12